

CERTIFICATE OF ANALYSIS

Fulmont Laboratory & Consultants
 219 Noonan Road
 Ft. Johnson, New York 12070
 Phone/Fax: (518) 842-5171

Date: November 3, 2016

Sample ID: 16111

Date(s) Analyzed: 10/21/16 - 11/1/16

WO Number: 160926111

Customer: Northville Central Schools

Collection Date: 9/26/16 & 9/29/16

Address: 131 South 3rd Street, Northville, New York 12134

Collection Time: See Chart

Sample Location: Northville Central School K - 12

Collected by: Angelo E. Finateri

Sample Point: See Chart

Potable: Yes

Water Source: Municipal Water

Grab/Composite: Grab

Chlorinated: Yes

Receipt Temp:

Sample #	Northville Central School Sample Point	Collection Time	Date	Test Result (mg/l)	MCL (mg/l)	Qualifier	Method
83	Maintenance storage area sink	5:01 AM	9/26/16	0.015	0.015		SM3113B
58	Fountain next to kitchen-lower level	5:03 AM	9/26/16	<0.001	0.015		SM3113B
61	Kitchen slop sink	5:04 AM	9/26/16	0.002	0.015		SM3113B
78	Kitchen right sink	5:06 AM	9/26/16	0.003	0.015		SM3113B
82	Kitchen right small sink	5:06 AM	9/26/16	0.006	0.015		SM3113B
65	Kitchen left sink	5:07 AM	9/26/16	0.003	0.015		SM3113B
74	Rm LL 13 sink	5:08 AM	9/26/16	0.270	0.015	X	SM3113B
76	Rm LL 12 Art room Left spout	5:09 AM	9/26/16	0.008	0.015		SM3113B
79	Rm LL 12 Art room right spout	5:10 AM	9/26/16	0.004	0.015		SM3113B
60	Maintenance shop sink	5:11 AM	9/26/16	0.003	0.015		SM3113B
73	Maintenance shop drinking fountain	5:12 AM	9/26/16	0.007	0.015		SM3113B
41	LL 15 Teachers room	5:13 AM	9/26/16	0.004	0.015		SM3113B
75	Band room	5:15 AM	9/26/16	0.004	0.015		SM3113B
67	Fountain across from Rm 101	5:18 AM	9/26/16	<0.001	0.015		SM3113B
53	Rm 101 sink	5:19 AM	9/26/16	0.640	0.015	X	SM3113B
56	Men's bathroom next to 101-left	5:20 AM	9/26/16	0.004	0.015		SM3113B
57	Men's bathroom next to 101-right	5:20 AM	9/26/16	0.023	0.015	X	SM3113B
47	Rm 117 counter sink	5:22 AM	9/26/16	0.006	0.015		SM3113B
40	Rm 117 Bathroom sink	5:23 AM	9/26/16	0.005	0.015		SM3113B
33	Shop - left sink	5:24 AM	9/26/16	0.010	0.015		SM3113B
55	Shop - right sink	5:25 AM	9/26/16	0.010	0.015		SM3113B
39	Rm 104 sink	5:26 AM	9/26/16	0.002	0.015		SM3113B
19	Superintendent's Bathroom	5:28 AM	9/26/16	0.028	0.015	X	SM3113B
20	Superintendent's Office Bathroom - Laurie's	5:28 AM	9/26/16	0.005	0.015		SM3113B

CERTIFICATE OF ANALYSIS

Fulmont Laboratory & Consultants
 219 Noonan Road
 Ft. Johnson, New York 12070
 Phone/Fax: (518) 842-5171

Date: November 3, 2016

Sample ID: 16111

Date(s) Analyzed: 10/21/16 - 11/1/16

WO Number: 160926111

Customer: Northville Central Schools

Collection Date: 9/26/16 & 9/29/16

Address: 131 South 3rd Street, Northville, New York 12134

Collection Time: See Chart

Sample Location: Northville Central School K - 12

Collected by: Angelo E. Finateri

Sample Point: See Chart

Potable: Yes

Water Source: Municipal Water

Grab/Composite: Grab

Chlorinated: Yes

Receipt Temp:

Sample #	Northville Central School Sample Point	Collection Time	Date	Test Result (mg/l)	MCL (mg/l)	Qualifiers	Method
2	Rm 122 Teacher's room	5:30 AM	9/26/16	0.007	0.015		SM3113B
5	Nurse's office bathroom	5:31 AM	9/26/16	0.057	0.015	X	SM3113B
13	Pre-K room sink	5:32 AM	9/26/16	0.060	0.015	X	SM3113B
21	Auditorium green room sink	5:33 AM	9/26/16	0.007	0.015		SM3113B
6	General store room 113	5:35 AM	9/26/16	0.001	0.015		SM3113B
8	Girl's bathroom next to rm 130 - left	5:37 AM	9/26/16	0.022	0.015	X	SM3113B
4	Girl's bathroom next to rm 130 - right	5:37 AM	9/26/16	0.029	0.015	X	SM3113B
14	Room 147 sink	5:38 AM	9/26/16	0.012	0.015		SM3113B
7	Room 147 sink fountain	5:40 AM	9/26/16	0.003	0.015		SM3113B
50	Room 147 sink faucet	5:40 AM	9/26/16	0.007	0.015		SM3113B
10	Room 148 sink	5:41 AM	9/26/16	0.004	0.015		SM3113B
30	Room 148 sink fountain	5:42 AM	9/26/16	0.016	0.015	X	SM3113B
9	Room 149 sink	5:44 AM	9/26/16	0.006	0.015		SM3113B
3	Room 149 sink fountain	5:45 AM	9/26/16	0.003	0.015		SM3113B
12	Room 150 sink	5:46 AM	9/26/16	0.008	0.015		SM3113B
11	Room 156 Boy's PE office	5:48 AM	9/26/16	0.004	0.015		SM3113B
1	Room 157 Boy's locker room left sink	5:50 AM	9/26/16	0.008	0.015		SM3113B
17	Room 157 Boy's locker room right sink	5:50 AM	9/26/16	0.009	0.015		SM3113B
36	Room 157 Boy's locker room fountain	5:51 AM	9/26/16	0.004	0.015		SM3113B
18	Room 158 Girl's locker room left sink	5:52 AM	9/26/16	0.006	0.015		SM3113B
31	Room 158 girl's locker room right sink	5:53 AM	9/26/16	0.007	0.015		SM3113B
25	Room 158 Girl's locker room fountain	5:54 AM	9/26/16	0.016	0.015	X	SM3113B
23	Room 159 Girl's PE office	5:56 AM	9/26/16	0.012	0.015		SM3113B
27	Drinking fountain next to rm 159	5:58 AM	9/26/16	<0.001	0.015		SM3113B

CERTIFICATE OF ANALYSIS

Fulmont Laboratory & Consultants
 219 Noonan Road
 Ft. Johnson, New York 12070
 Phone/Fax: (518) 842-5171

Date: November 3, 2016

Sample ID: 16111

Date(s) Analyzed: 10/21/16 - 11/1/16

WO Number: 160926111

Customer: Northville Central Schools
 Address: 131 South 3rd Street, Northville, New York 12134
 Sample Location: Northville Central School K - 12
 Sample Point: See Chart
 Water Source: Municipal Water
 Chlorinated: Yes

Collection Date: 9/26/16 & 9/29/16
 Collection Time: See Chart
 Collected by: Angelo E. Finateri
 Potable: Yes
 Grab/Composite: Grab
 Receipt Temp:

Sample #	Northville Central School Sample Point	Collection Time	Date	Test Result (mg/l)	MCL (mg/l)	Qualifiers	Method
16	Fountain bottle fill next to rm 159	5:59 AM	9/26/16	<0.001	0.015		SM3113B
38	Custodian slop sink next to rm 159	6:00 AM	9/26/16	0.006	0.015		SM3113B
34	Girl's public bathroom - gym area - left	6:01 AM	9/26/16	0.073	0.015	X	SM3113B
26	Girl's public bathroom - gym area - right	6:01 AM	9/26/16	0.076	0.015	X	SM3113B
22	Rm 161 refreshment booth	6:02 AM	9/26/16	0.730	0.015	X	SM3113B
43	Boy's public bathroom - gym area - left	6:03 AM	9/26/16	0.027	0.015	X	SM3113B
28	Boy's public bathroom - gym area - right (leaking)	6:04 AM	9/26/16	0.043	0.015	X	SM3113B
Ice mouth bottle	Ice Machine in Gym area - Rm 155	6:07 AM	9/26/16	<0.001	0.015		SM3113B
119	98 Wing first floor drinking fountain	6:00 AM	9/27/16	<0.001	0.015		SM3113B
32	98 Wing first floor drinking fountain bottle fill	6:09 AM	9/26/16	<0.001	0.015		SM3113B
44	Room 143 sink fountain	6:12 AM	9/26/16	<0.001	0.015		SM3113B
62	Room 143 sink	6:12 AM	9/26/16	<0.001	0.015		SM3113B
45	Room 134 sink fountain	6:13 AM	9/26/16	<0.001	0.015		SM3113B
35	Room 134 sink	6:14 AM	9/26/16	0.007	0.015		SM3113B
112	Room 142 sink fountain	6:05 AM	9/29/16	<0.001	0.015		SM3113B
42	Room 142 sink	6:15 AM	9/26/16	<0.001	0.015		SM3113B
63	Woman's family bathroom	6:17 AM	9/26/16	0.025	0.015	X	SM3113B
24	Men's room next to Family bathroom	6:18 AM	9/26/16	0.014	0.015		SM3113B
51	Custodian sink next to Family bathroom	6:19 AM	9/26/16	0.006	0.015		SM3113B
89	Room 139 sink fountain	6:19 AM	9/26/16	<0.001	0.015		SM3113B
46	Room 139 sink	6:20 AM	9/26/16	<0.001	0.015		SM3113B
59	Room 140 sink fountain	6:21 AM	9/26/16	0.001	0.015		SM3113B
48	Room 140 sink	6:21 AM	9/26/16	0.002	0.015		SM3113B
121	Room 141 sink fountain	6:06 AM	9/29/16	<0.001	0.015		SM3113B

CERTIFICATE OF ANALYSIS

Fulmont Laboratory & Consultants
 219 Noonan Road
 Ft. Johnson, New York 12070
 Phone/Fax: (518) 842-5171

Date: November 3, 2016

Sample ID: 16111

Date(s) Analyzed: 10/21/16 - 11/1/16

WO Number: 160926111

Customer: Northville Central Schools

Collection Date: 9/26/16 & 9/29/16

Address: 131 South 3rd Street, Northville, New York 12134

Collection Time: See Chart

Sample Location: Northville Central School K - 12

Collected by: Angelo E. Finateri

Sample Point: See Chart

Potable: Yes

Water Source: Municipal Water

Grab/Composite: Grab

Chlorinated: Yes

Receipt Temp:

Sample #	Northville Central School Sample Point	Collection Time	Date	Test Result (mg/l)	MCL (mg/l)	Qualifiers	Method
52	Room 141 sink	6:23 AM	9/26/16	0.001	0.015		SM3113B
72	Custodian slop sink LL 98 wing	6:26 AM	9/26/16	0.004	0.015		SM3113B
69	Room LL 30 library sink	6:28 AM	9/26/16	0.075	0.015	X	SM3113B
66	LL 98 wing fountain	6:29 AM	9/26/16	<0.001	0.015		SM3113B
15	LL 98 wing fountain bottle fill	6:29 AM	9/26/16	<0.001	0.015		SM3113B
80	2nd floor 98 wing family bathroom	6:32 AM	9/26/16	0.009	0.015		SM3113B
86	2nd floor 98 wing men's bathroom	6:32 AM	9/26/16	0.018	0.015	X	SM3113B
68	Custodian slop sink - 98 wing - next to family bathroom	6:33 AM	9/26/16	0.003	0.015		SM3113B
77	Room 230 sink fountain	6:34 AM	9/26/16	0.001	0.015		SM3113B
54	Room 230 sink	6:35 AM	9/26/16	0.004	0.015		SM3113B
84	2nd floor 98 wing fountain	6:37 AM	9/26/16	<0.001	0.015		SM3113B
81	2nd floor 98 wing fountain bottle fill	6:37 AM	9/26/16	<0.001	0.015		SM3113B
87	Room 237 sink by entrance - sink #1	6:39 AM	9/26/16	0.006	0.015		SM3113B
64	Room 237 left sink - far wall - sink #2	6:40 AM	9/26/16	0.020	0.015	X	SM3113B
70	Room 237 - right sink - far wall - sink #3	6:41 AM	9/26/16	0.002	0.015		SM3113B
90	Room 238 sink	6:43 AM	9/26/16	0.012	0.015		SM3113B
88	Fountain next to room 240	6:44 AM	9/26/16	<0.001	0.015		SM3113B
71	Fountain bottle fill next to room 240	6:44 AM	9/26/16	<0.001	0.015		SM3113B
85	Room 239 sink by doorway #1	6:46 AM	9/26/16	0.004	0.015		SM3113B
91	Room 239 sink by doorway #2	6:49 AM	9/26/16	0.009	0.015		SM3113B
92	Room 239 sink by doorway #3	6:49 AM	9/26/16	0.010	0.015		SM3113B
93	Room 239 sink by doorway - #4	6:50 AM	9/26/16	0.014	0.015		SM3113B
98	Girl's bathroom by balcony - left	7:04 AM	9/26/16	0.002	0.015		SM3113B
99	Girl's bathroom by balcony - right	7:04 AM	9/26/16	0.004	0.015		SM3113B

CERTIFICATE OF ANALYSIS

Fulmont Laboratory & Consultants
 219 Noonan Road
 Ft. Johnson, New York 12070
 Phone/Fax: (518) 842-5171

Date: November 3, 2016

Sample ID: 16111

Date(s) Analyzed: 10/21/16 - 11/1/16

WO Number: 160926111

Customer: Northville Central Schools
 Address: 131 South 3rd Street, Northville, New York 12134
 Sample Location: Northville Central School K - 12
 Sample Point: See Chart
 Water Source: Municipal Water
 Chlorinated: Yes

Collection Date: 9/26/16 & 9/29/16
 Collection Time: See Chart
 Collected by: Angelo E. Finateri
 Potable: Yes
 Grab/Composite: Grab
 Receipt Temp:

Sample #	Northville Central School Sample Point	Collection Time	Date	Test Result (mg/l)	MCL (mg/l)	Qualifiers	Method
94	Room 240 sink #1	6:53 AM	9/26/16	0.008	0.015		SM3113B
95	Room 240 sink #2	6:56 AM	9/26/16	0.008	0.015		SM3113B
96	Room 240 sink #3	6:58 AM	9/26/16	0.016	0.015	X	SM3113B
97	Room 240 sink #4	6:59 AM	9/26/16	0.009	0.015		SM3113B
100	Teacher's room 2nd floor	7:07 AM	9/26/16	0.015	0.015		SM3113B
102	Room 210 sink #1 left	7:12 AM	9/26/16	0.056	0.015	X	SM3113B
101	Room 210 sink #1 right	7:13 AM	9/26/16	0.110	0.015	X	SM3113B
103	Room 210 sink #2 left	7:13 AM	9/26/16	0.130	0.015	X	SM3113B
104	Room 210 sink #2 right	7:14 AM	9/26/16	0.290	0.015	X	SM3113B
105	Room 210 sink #3 left	7:14 AM	9/26/16	0.190	0.015	X	SM3113B
106	Room 210 sink #3 right	7:15 AM	9/26/16	0.070	0.015	X	SM3113B
107	Room 210 sink #4 left	7:16 AM	9/26/16	0.045	0.015	X	SM3113B
108	Room 210 sink #4 right	7:16 AM	9/26/16	0.096	0.015	X	SM3113B
109	Room 210 sink #5 left	7:16 AM	9/26/16	0.240	0.015	X	SM3113B
110	Room 210 sink #5 right	7:17 AM	9/26/16	0.073	0.015	X	SM3113B
111	Room 210 sink #6 left	7:17 AM	9/26/16	0.100	0.015	X	SM3113B
115	Room 210 sink #6 right	6:24 AM	9/29/16	0.011	0.015		SM3113B
125	Drinking fountain by HS office	6:14 AM	9/29/16	<0.001	0.015		SM3113B
116	Drinking fountain bottle fill by HS office	6:15 AM	9/29/16	<0.001	0.015		SM3113B
113	Men's room by HS office - left sink	6:20 AM	9/29/16	0.002	0.015		SM3113B
114	Men's room by HS office - right sink	6:21 AM	9/29/16	0.004	0.015		SM3113B
117	Room 201 sink	7:23 AM	9/26/16	0.050	0.015	X	SM3113B
118	Art room sink #1	7:21 AM	9/26/16	0.007	0.015		SM3113B
126	Art room sink #2	6:18 AM	9/29/16	0.019	0.015	X	SM3113B

CERTIFICATE OF ANALYSIS

Fulmont Laboratory & Consultants
 219 Noonan Road
 Ft. Johnson, New York 12070
 Phone/Fax: (518) 842-5171

Date: November 3, 2016

Sample ID: 16111

Date(s) Analyzed: 10/21/16 - 11/1/16

WO Number: 160926111

Customer: Northville Central Schools

Collection Date: 9/26/16 & 9/29/16

Address: 131 South 3rd Street, Northville, New York 12134

Collection Time: See Chart

Sample Location: Northville Central School K - 12

Collected by: Angelo E. Finateri

Sample Point: See Chart

Potable: Yes

Water Source: Municipal Water

Grab/Composite: Grab

Chlorinated: Yes

Receipt Temp:

Sample #	Northville Central School Sample Point	Collection Time	Date	Test Result (mg/l)	MCL (mg/l)	Qualifiers	Method
122	Fountain bottle fill across from room 101	6:31 AM	9/29/16	<0.001	0.015		SM3113B
124	LL fountain bottle fill	6:33 AM	9/29/16	<0.001	0.015		SM3113B
120	Outside faucet bottle fill	6:41 AM	9/29/16	<0.001	0.015		SM3113B
123	Outside playground fountain	6:38 AM	9/29/16	0.001	0.015		SM3113B

MCL = Maximum Contaminant Level referenced from New York State Subpart 5-1 of the Public Drinking Water Standards and/or National Primary/Secondary Drinking Water Standards.

Comments:

Not all test results are within acceptable limits, please consult chart. Test procedures for all analyses meet NELAC requirements unless noted. If you have any questions, please call the laboratory.

Qualifiers Key:

X - Exceeds maximum contamination limit	R - Duplication outside acceptance limits	H - Hold time exceeded
T - Temperature outside specifications	A - Sample contained air bubble or headspace	B - Analyte detected in blank
S(+/-) Lab control sample outside acceptable limits	M(+/-) Matrix spike recovery outside acceptance limits	
(+) Result may be biased high		
(-) Result may be biased low		

Legend:
 < = Less than
 > = Greater than
 ≈ = Approximately
 NP = Not Provided
 mg/l = milligrams per liter = ppm
 ppm = parts per million
 µg/l = micrograms per liter = ppb
 ppb = parts per billion
 gpg = grains per gallon
 MCL = Maximum Contaminant Level
 SM = Standard Methods For the Examination of Water and Wastewater

Reviewed by Angelo E. Finateri Angelo E. Finateri

Environmental Laboratory NYSDOH E.L.A.P. #10350